ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0673	NA	Kempe gowda nagara colony
Segment No.	**Total Length (m)**	
9/S-W0673/S043202	210.09	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	210.09	77.567099	13.066660	77.567692	13.068305	W0675	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Estimate for Improvements to roads and Drains at Kempe gowda nagara colony in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zo	1442000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Estimate for Improvements to roads and Drains at Kempe gowda nagara colony in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	009-16-000055
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/93/2016-17	05/08/2016	180 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
05/08/2016	01/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL BANGALORE		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		JANARDHAN

Date of Inspection	Remarks
29/10/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	29/10/2016	28/11/2016	COMPLETED
SE	VASU K M	29/10/2016	28/11/2016	COMPLETED
EE	YARAPPA REDDY	29/10/2016	28/11/2016	COMPLETED
AEE	SHIVAKUMAR	29/10/2016	28/11/2016	COMPLETED
AE	JANARDHAN	29/10/2016	28/11/2016	COMPLETED
AE	JANARDHAN	29/10/2016	28/11/2016	COMPLETED